


EZ Clean LOW MAINTENANCE Tile Flange

Our exclusive EZ Clean Tile Flange not only enhances the beauty of your Hydro Massage tub, it also effectively eliminates water leakage and reduces mold and mildew problems on the caulking at the deck of the bath



Dual Stage Tile Flange



Dual Stage Tile Flange
with Tile Installed

No Scrubbing

Just Wipe Down & You're Done!

Older tubs and some competitors models have caulking between the deck of the bath and the tile. The caulking tends to erode and absorb contaminants, causing a black layer of bacteria, mold and mildew to accumulate.



Black Mold Caulking
at Tub Deck